

## Test Leads

### AL-56FL



CE

- AL-56FL is an ideal tool which shows the indication of live voltage even with blown fuse
- 2 replaceable fast-acting fuses (1000V, 11A with internal rating of 20kA AC/DC)
- Fuses provide additional testing protection
- Helps to prevent a possible mis-indication when there is voltage present
- CAT III 1000V, CAT IV 600V, 10A with protective cover
- 2mm probe tips, removable 4mm brass caged banana probe tips are also included
- Includes high-quality silicone test leads, 1.5m
- Wipe the fused test probes and silicone test leads periodically with a damp cloth and detergent. Do not use abrasives or solvents
- Operating temperature: -20°C~50°C (-5°F to 120°F)
- One year warranty
- Can't be used in amperage mode with blown fuse
- Rating:  
EN 61010-031 CAT III 1kV 10A / CAT IV 600V 10A

### AL-57FL



CE

- AL-57FL is an ideal tool which shows the indication of live voltage even with blown fuse
- 2 replaceable fast-acting fuses (1000V, 11A with internal rating of 20kA AC/DC)
- Fuses provide additional testing protection
- Helps to prevent a possible mis-indication when there is voltage present
- CAT III 1000V, CAT IV 600V, 10A with protective cover
- 2mm probe tips, removable 4mm brass caged banana probe tips are also included
- Includes high-quality silicone test leads, 1.5m
- Wipe the fused test probes and silicone test leads periodically with a damp cloth and detergent. Do not use abrasives or solvents
- Operating temperature: -20°C~50°C (-5°F to 120°F)
- One year warranty
- Can't be used in amperage mode with blown fuse
- Rating:  
EN 61010-031 CAT III 1kV 10A / CAT IV 600V 10A